

MAZDA 3 (BM)

5-Door

10/13 - 07/16


4-Door 10/13 - 07/16

Mazda 3 (BN)

08/16 >>

08/16>>

Part No. 750005



Installation instructions


Reference:


The following information must be reviewed before beginning the assembly:


The installation instructions are to be thoroughly read.

The installation should be carried out by qualified personnel with the relevant technical knowledge. The vehicle manufacturers' current technical notices and information on retrofitting must be followed. The removal and replacement instructions found in the current repair manuals must be followed.


It must be ensured that the vehicle is technically suitable for the installation of a trailer hitch.







TOOLS



(BM) Vehicle without PDC (10/13-07/16)









(BM) Higher Spec Vehicles (10/13-07/16)

OPTION2




(BM) Base Models (10/13-07/16)

OPTION3



(BN) Models (08/16 >>)


OPTION 4








Also BM Models with no matching connections in the connector on the vehicle side.

750005e190318B8 5 / 28


















In case of wrong pin insert:













750005e190318B8 10 / 28


























| 1 | ye | \triangleleft |
|---|----|-----------------|
| 2 | bk | 1 3 2 4 R |
| 3 | wh | = |
| 4 | gn | |
| 5 | bu | (O) |
| 6 | rd | Stop |
| 7 | bn | |

| 9 | bk | wh | gy | gn | rd | bu | ye | bn | pu | or | no |
|----|-------|-------|------|-------|-----|------|--------|-------|--------|--------|-----------------|
| GB | black | white | grey | green | red | blue | yellow | brown | purple | orange | not occupied |




750005e190318B8 12 / 28






13 OPTION 1 – Vehicles without PDC





14 OPTION 2 – (BM) Higher Spec. Vehicles (10/13 – 07/16)




750005e190318B8 14 / 28









16 OPTION 3 – (BM) Base Models (10/13 – 07/16)



750005e190318B8 15 / 28













(BN) Models 08/16 >>



750005e190318B8 16 / 28

19 OPTION 4

(BN) Models 08/16 >>





20 OPTION 4








(BN) Models 08/16 >>





























750005e190318B8 22 / 28


30 OPTIONAL






























31





750005e190318B8 23 / 28

CHECK ALL LIGHTING FUNCTIONS




CHECK BULB OUT DETECTION 33





750005e190318B8 24 / 28





Subject to change in terms of construction, equipment and colour, and may contain errors.

The information and illustrations are non-binding.

750005e190318B8 28 / 28